



Front south exposure of Recreation Park 1936 Bathhouse



Back north exposure of Recreation Park 1936 Bathhouse



West exposure of building with fireplace in the
Women's Lounge

Arlington Heights Park District
MITIGATION- 1939 Recreation Park Bathhouse

SHPO LOG# 009011124



Club Room with fireplace on the east wall of the main entrance.



Close up of the Club Room fireplace.



Women's Lounge fireplace on west wall.



Board Room- Cabinets on the north wall

Arlington Heights Park District
MITIGATION- 1939 Recreation Park Bathhouse

SHPO LOG# 009011124

