





North east view of 1936 Bath House, pool, and 1963 Pool House.




East view of pool house



South east view of pool house




South front entrance of Recreation Pool house at Douglas & Miner Streets




Pool house entrance and south wing to Locker rooms and the Pool Mechanical and Storage rooms.



West entrance doors from the Wading Pool
and outside toilets.



Outside toilet rooms on northside of building 1 of 3



Interior of toilet room 2 of 3



Interior of toilet room 3 of 3




Entrance at pool cashier desk looking south. Spheroidal glass lights above.



Facing south west, approach to pool cashier desk



Pool cashier desk facing west and leading to Concessions area. Spheroidal glass lights above.



East view of the Concessions area towards Entrance.

Arlington Heights Park District
MITIGATION- 1963 Recreation Park Pool House

SHPO LOG# 009011124




North east view from Concessions area.




West view from entrance towards Wading pool and walkway to manager office and locker rooms.



Plaque on west wall outside Pool Managers Office




Entrance to Pool Managers Office- facing west 1 of 2




Inside Pool Managers Office facing east 2 of 2



Southeast approach to Men's and Women's Locker rooms. Entrance to Women's locker room is through the glass double doors. Locker rooms lead to showers and the main pool.




Custodial closet



Men's Locker room facing north west. Entrance to Custodial Closet ① and Showers ② in foreground.

Arlington Heights Park District
MITIGATION- 1963 Recreation Park Pool House

SHPO LOG# 009011124




Men's toilet room 1 of 2



Men's toilet room 2 of 2




South wing to Women's locker room, showers,
and pool entrance.



Women's Locker room looking east

Arlington Heights Park District
MITIGATION- 1963 Recreation Park Pool House

SHPO LOG# 009011124



Women's locker room facing west. Changing stall entrance on the far left ①, shower entrance ②, and toilet room entrance ③.



Changing stalls facing south.



Shower stalls facing north. Photo taken from pool entrance.




Women's toilet room-west.

Arlington Heights Park District
MITIGATION- 1963 Recreation Park Pool House


SHPO LOG# 009011124




Pool Mechanical room, west view 1 of 3




Pool Mechanical room, south wall 2 of 3



Pool Mechanical room, facing south 3 of 3



Pool Storage room, facing south west



Entrance to Pool Mechanical and Storage rooms,
facing south